

INSPECTION REPORT

End of contract

GENERAL INFO

File	312254
License plate	2BTV163
Vehicle identification number	W1K1186841N296252
Dossier	2021 221 107
Make	Mercedes CLA SB 180 Busin.Solu
Mileage	40158
First registration	21/03/2022
client availability date	19/05/2026
inspectionDate	20/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
83	Door Front Left // Painting	N
104	Door Rear Left // Repair & Painting	N
132	Bumper Rear // Smart Repair Large	N
180	Wing Rear Right // Smart Repair Small	N
194	Door Rear Right // Repair & Painting	N
210	Door Front Right // Smart Repair Small	Y
230	Wing Front right // Smart Repair Small	Y
883	Key Price Range 2 //	N

Damage Pictures



Damage within Renta-norm-



Bumper Rear // Smart Repair Large-scratch



Door Front Left // Painting-scratch




Wing Rear Right // Smart Repair Small-dent



Door Rear Left // Repair & Painting-scratch + dent




Wing Front right // Smart Repair Small-scratch + dent



Door Front Right // Smart Repair Small-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Key Price Range 2 //-missing