

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	313012
License plate	2DCJ431
Vehicle identification number	W1K5M1CBXPN349960
Dossier	2022 084 007
Make	Mercedes CLA SB 200 d Business
Mileage	101075
First registration	01/02/2023
client availability date	15/05/2026
inspectionDate	22/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	







## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
41	Windshield // Replace	Y
54	Headlight / Front left / Replace	N
92	Rocker Panel Left // Painting	Y
106	Door Rear Left // Polish	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
162	Roof // Painting	N
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
202	Rocker Panel Right // Painting	Y
216	Door Front Right // Polish	Y
217	Door Front Right / Trim / Replace	Y
219	Door Front Right / Window / Replace	Y
222	Side View Mirror Right // Painting	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
569	Dashboard / Steering Wheel / Replace	Y

## Damage Pictures



Light / Rear left / Replace-scratch





Light / Rear Right / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Wheel Alloy Rear Right // Repair-scratch






Wing Rear Right // Polish-scratch



Door Rear Right // Polish-scratch



Door Front Right // Polish-scratch




Rocker Panel Right // Painting-scratch



Door Front Right / Trim / Replace-scratch



Door Front Right / Window / Replace-scratch



Side View Mirror Right // Painting-scratch



Wing Front right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Headlight / Front left / Replace-scratch



Front Bonnet // Polish-scratch



Windshield // Replace-scratch



Wheel Alloy Front Left // Repair-scratch




Door Rear Left // Polish-scratch



Rocker Panel Left // Painting-scratch



Roof // Painting-scratch



Wing Rear Left // Smart Repair Small-dent



Bumper Front // Painting-bad repair



Bumper Rear // Painting-bad repair



Dashboard / Steering Wheel / Replace-worn