

INSPECTION REPORT


End of contract

GENERAL INFO

File	314865
License plate	2HAP727
Vehicle identification number	W1VTBACZ2RU389990
Dossier	2025087026
Make	Mercedes Citan 110 CDI L1 Base
Mileage	38407
First registration	14/05/2025
client availability date	15/06/2026
inspectionDate	17/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
41	Windshield // Replace	N

Damage Pictures



Bumper Front // Replace & Painting-cracked



Windshield // Replace-glass damage