

# INSPECTION REPORT


End of contract


## GENERAL INFO

File	309905
License plate	2AUW677
Vehicle identification number	W1K1183861N246978
Dossier	2021106038
Make	Mercedes CLA 250 e Bus.Solut.A
Mileage	146983
First registration	28/07/2021
client availability date	06/04/2026
inspectionDate	15/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	Y
40	Windshield // Repair	Y
66	Wing Front Left // Polish	Y
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
165	Roof // Polish	Y
203	Rocker Panel Right // Repair & Painting	Y
213	Door Front Right // Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	Y
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
421	Seat Front Right // Repair	N
431	Seat Rear Left // Repair	Y
432	Seat Rear Left / Bottom Coating / Replace	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
560	Interior / A Pillar Cover / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	Y
850	Certificate of Conformity //	N
851	Registration Card loss Arval name //	N
860	Interior Cleaning // Small	N

Damage Pictures



See External Expertise-





Door Front Right // Painting-scratch



Bumper Rear // Painting-scratch



Light / Rear left / Replace-scratch





Rear Bonnet // Polish-scratch




Wing Front Left // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Front Bonnet // Painting-scratch



Roof // Polish-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Rocker Panel Right // Repair & Painting-scratch



Interior / Side Cover rear Seat / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Seat Rear Left // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-cracked



Side View Mirror Right / Direction Indicator / Replace-cracked




Seat Front Right // Repair-Incinerated




Seat Rear Left / Bottom Coating / Replace-Incinerated



Interior / A Pillar Cover / Replace-Incinerated




Interior // Repair 1-Incinerated



Windshield // Repair-glass damage



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn