

INSPECTION REPORT


End of contract

GENERAL INFO

File	317317
License plate	ZG5397
Vehicle identification number	ZACPJFCW2RPS85318
Dossier	2024066024
Make	Jeep Co.1.3PHEV 190 eAWD Altit
Mileage	33780
First registration	24/07/2024
client availability date	03/07/2026
inspectionDate	08/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	Y
31	Front Bonnet // Smart Repair Small	N
84	Door Front Left // Repair & Painting	Y
100	Door Rear Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	N
174	Light / Rear Right / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
236	Wing Front right // Polish	Y
271	Bumper Front / Trim Left / Replace	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
543	Interior // Ionization Odor	N

Damage Pictures



Door Rear Right // Polish-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Rear // Polish-scratch



Light / Rear Right / Replace-scratch



Light / Rear left / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Smart Repair Small-dent



Wing Rear Left // Smart Repair Small-dent




Door Rear Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Front Bonnet // Smart Repair Small-dent



Door Front Left // Repair & Painting-scratch + dent