

INSPECTION REPORT


End of contract

GENERAL INFO

File	313412
License plate	2CKT992
Vehicle identification number	TMAJD81BGNJ231129
Dossier	2022228082
Make	Hyundai Tuc.T-GDi 48V 110kW Fe
Mileage	72689
First registration	29/08/2022
client availability date	25/05/2026
inspectionDate	19/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
187	Wing Rear Right / Trim / Replace	N
193	Door Rear Right // Painting	N
132	Bumper Rear // Smart Repair Large	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
281	Bumper Rear / Trim Left / Replace	N
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	N
28	Front / Calendar / Replace	Y
35	Front Bonnet // Polish	Y
72	Side View Mirror Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
107	Door Rear Left / Trim / Replace	N
116	Wing Rear Left // Polish	Y
118	Wing Rear Left / Fuel Cover / Replace	Y
156	Rear Bonnet // Polish	Y
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
162	Roof // Painting	Y
165	Roof // Polish	Y
167	Roof / Roof Rails / Replace	Y
167	Roof / Roof Rails / Replace	Y
186	Wing Rear Right // Polish	Y
214	Door Front Right // Repair & Painting	N
233	Wing Front right // Painting	Y
271	Bumper Front / Trim Left / Replace	N

272	Bumper Front / Trim Right / Replace	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
840	Interior Cleaning // Large	N
850	Certificate of Conformity //	N
859	Display Navigation-Radio // Replace	N
883	Key Price Range 2 //	Y

Damage Pictures



Rear Bonnet // Polish-scratch




Rear Bonnet // Polish-scratch



Wing Rear Right // Polish-scratch




Wheel Two Tone Rear Right // Repair-scratch



Display Navigation-Radio // Replace-scratch



Roof / Roof Rails / Replace-scratch



Roof // Polish-scratch



Roof // Painting-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Trim Right / Replace-scratch




Bumper Front // Painting-scratch



Front / Calendar / Replace-scratch



Front Bonnet // Polish-scratch



Side View Mirror Left // Painting-scratch



Door Rear Left // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Painting-scratch



Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Roof // Smart Repair Medium-dent



Bumper Front / Trim Left / Replace-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left / Trim / Replace-scratch + dent



Door Front Right // Repair & Painting-scratch + dent





Interior Cleaning // Large-stain



Key Price Range 2 //-worn



Wing Rear Left / Fuel Cover / Replace-bad position



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Trim Left / Replace-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Smart Repair Large-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Side View Mirror Right // Painting-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Door Rear Right // Painting-scratch