

INSPECTION REPORT

End of contract

GENERAL INFO

File	315940
License plate	SY9448
Vehicle identification number	VSSZZZKL1SR110626
Dossier	2025072001
Make	Seat Leon 1.5TSI 150 Style
Mileage	38320
First registration	20/06/2025
client availability date	22/06/2026
inspectionDate	25/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
80	Door Front Left // Smart Repair Small	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
199	Door Rear Right / Window / Replace	N
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
549	Interior / Headliner/ Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N
881	Key Price Range 1 //	N

Damage Pictures



Wheel Alloy Front Right // Repair-scratch



Rear Right Door Interior Coating // Repair-scratch



Door Rear Right / Window / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Polish-scratch



Wing Rear Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Interior / Headliner/ Replace-tear



Interior Cleaning // Small-stain