

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	308008
License plate	1XHZ255
Vehicle identification number	VF3VFAHKKKZ090873
Dossier	2019183067
Make	Peugeot Expert 2.0BHDi 120 L3
Mileage	140387
First registration	13/01/2020
client availability date	13/03/2026
inspectionDate	31/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







## DAMAGES

Damages	Type	Acceptable
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	N
12	Bumper Front // Smart Repair Large	N
13	Bumper Front // Painting	Y
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
114	Wing Rear Left // Repair & Painting	N
137	Bumper Rear // Replace without painting	N
162	Roof // Painting	N
180	Wing Rear Right // Smart Repair Small	Y
193	Door Rear Right // Painting	Y
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
231	Wing Front right // Smart Repair Medium	N
291	Rear Loading Door Left // Smart Repair Medium	N
303	Rear Loading Door Right // Painting	N
314	Wheel Front Left / Wheel Cover / Replace	N
412	Seat Front Left / Bottom Coating / Replace	Y
531	Trunk Compartment // Repair	Y
569	Dashboard / Steering Wheel / Replace	Y

## Damage Pictures



Rear Loading Door Left // Smart Repair Medium-scratch + dent




Wing Rear Left // Repair & Painting-scratch + dent



Wheel Front Left / Wheel Cover / Replace-missing





Dashboard / Steering Wheel / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn



Roof // Painting-Chipped paint



Door Rear Right // Painting-scratch



Door Rear Right / Trim / Replace-scratch



Wing Rear Right // Smart Repair Small-dent



Wing Front right // Smart Repair Medium-dent




Rocker Panel Right // Smart Repair Medium-scratch + dent



Bumper Rear // Replace without painting-scratch



Trunk Compartment // Repair-scratch



Rear Loading Door Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Door Front Left // Painting-scratch




Bumper Front // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Door Front Right / Trim / Replace-scratch



Door Front Right // Repair & Painting-scratch + dent