

INSPECTION REPORT






End of contract


GENERAL INFO

File	319999
License plate	1YWS441
Vehicle identification number	TMBJJ7NX6MY085708
Dossier	2020275078
Make	Skoda Oct.Com.2.0TDI 110kW Sty
Mileage	91197
First registration	14/01/2021
client availability date	11/08/2026
inspectionDate	28/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
33	Front Bonnet // Repair & Painting	Y
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
106	Door Rear Left // Polish	Y
133	Bumper Rear // Painting	N
152	Rear Bonnet // Smart Repair Large	N
156	Rear Bonnet // Polish	Y
165	Roof // Polish	Y
174	Light / Rear Right / Replace	Y
194	Door Rear Right // Repair & Painting	N
203	Rocker Panel Right // Repair & Painting	N
213	Door Front Right // Painting	N
222	Side View Mirror Right // Painting	N
234	Wing Front right // Repair & Painting	N
282	Bumper Rear / Trim Center / Replace	N
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
342	Wheel Alloy Front Right // Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Light / Rear Right / Replace-scratch



Rear Bonnet // Polish-scratch



Bumper Rear / Trim Center / Replace-scratch



Bumper Rear // Painting-scratch



Door Rear Left // Polish-scratch



Wing Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Side View Mirror Right // Painting-scratch




Door Front Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rocker Panel Right // Repair & Painting-scratch + dent




Wheel Alloy Front Right // Replace-scratch + dent




Wing Front right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent




Windshield // Repair-cracked



Roof // Polish-Chemical reaction



Rear Bonnet // Smart Repair Large-Chemical reaction



Front Bonnet // Repair & Painting-stone chipping