

INSPECTION REPORT



End of contract

GENERAL INFO

File	313875
License plate	2CAX095
Vehicle identification number	TMAJD81BANJ185552
Dossier	2022124100
Make	Hyundai Tuc.T-GDi 48V 110kW Fe
Mileage	178129
First registration	16/05/2022
client availability date	01/06/2026
inspectionDate	18/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	N
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	N
110	Wing Rear Left // Smart Repair Small	N
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
540	Interior // Repair 1	N
541	Interior // Repair 2	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Polish-scratch




Wheel Two Tone Front Left // Repair-scratch




Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Rear Right // Polish-scratch



Wing Rear Left // Smart Repair Small-dent



Door Rear Left // Repair & Painting-scratch + dent




Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent




Door Front Left // Smart Repair Small-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Interior // Repair 1-cracked



Interior // Repair 2-missing



Interior Cleaning // Small-stain



Windshield // Repair-stone chipping