

INSPECTION REPORT



End of contract


GENERAL INFO

File	309713
License plate	SZ7647
Vehicle identification number	VSSZZKJZNR084320
Dossier	2021355022
Make	Seat Ibiza 1.0TSi 110 Style DS
Mileage	111651
First registration	30/03/2022
client availability date	01/04/2026
inspectionDate	08/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	Y
64	Wing Front Left // Repair & Painting	N
72	Side View Mirror Left // Painting	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
134	Bumper Rear // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
219	Door Front Right / Window / Replace	N
222	Side View Mirror Right // Painting	N
234	Wing Front right // Repair & Painting	N
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
553	Central Console / Gear Lever / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
648	Rear Right Door Interior Coating / Door Handle / Replace	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Wheel Alloy Rear Left // Repair-scratch



Door Front Left // Painting-scratch



Side View Mirror Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating / Door Handle / Replace-scratch




Door Front Right / Window / Replace-scratch




Side View Mirror Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-dent



Door Rear Right // Repair & Painting-dent



Wing Front right // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Windshield // Replace-cracked



Interior Cleaning // Small-stain



Central Console / Gear Lever / Replace-worn