

INSPECTION REPORT

End of contract

GENERAL INFO

File	310693
License plate	2BVW590
Vehicle identification number	W1N2539111V371650
Dossier	2021323020
Make	Mercedes GLC 300de 4M Bus.Sol.
Mileage	111613
First registration	12/04/2022
client availability date	20/04/2026
inspectionDate	04/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	






DAMAGES


Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
33	Front Bonnet // Repair & Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	N
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
196	Door Rear Right // Polish	Y
236	Wing Front right // Polish	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures






Damage within Renta-norm-



Door Rear Right // Polish-scratch





Wheel Two Tone Front Right // Repair-scratch




Wing Front right // Polish-scratch




Wheel Two Tone Rear Right // Repair-scratch



Light / Rear Right / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Rear Bonnet // Polish-scratch



Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Wing Rear Left // Polish-scratch



Door Rear Left // Polish-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Front Bonnet // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Wing Rear Right // Smart Repair Small-scratch + dent