

INSPECTION REPORT


End of contract

GENERAL INFO

File	321124
License plate	2CJY749
Vehicle identification number	1C4PJDDW1NP026882
Dossier	2022117113
Make	Jeep Ren.1.3PHEV190 4xeATX UpI
Mileage	78186
First registration	18/08/2022
client availability date	02/09/2026
inspectionDate	08/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
84	Door Front Left // Repair & Painting	N
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
117	Wing Rear Left / Trim / Replace	Y
124	Light / Rear left / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
153	Rear Bonnet // Painting	Y
190	Door Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	Y
237	Wing Front right / Trim / Replace	Y
422	Seat Front Right / Bottom Coating / Replace	N
531	Trunk Compartment // Repair	Y
553	Central Console / Gear Lever / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	N
860	Interior Cleaning // Small	Y

Damage Pictures



Wing Front right / Trim / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent




Door Front Left // Repair & Painting-scratch + dent




Door Front Right // Repair & Painting-scratch + dent



Seat Front Right / Bottom Coating / Replace-Incinerated



Interior Cleaning // Small-stain



Central Console / Gear Lever / Replace-hole




Door Rear Left // Polish-scratch




Wing Rear Left // Polish-scratch



Wing Rear Left / Trim / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Light / Rear left / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Rear Bonnet // Painting-scratch



Door Rear Right // Smart Repair Small-scratch



Trunk Compartment // Repair-scratch



Bumper Front // Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch