

INSPECTION REPORT







End of contract

GENERAL INFO

File	321252
License plate	2AFF803
Vehicle identification number	VSSZZZKJZMR113627
Dossier	2021 018 156
Make	Seat Arona 1.0 70kW Move
Mileage	118175
First registration	16/03/2021
client availability date	02/09/2026
inspectionDate	07/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
103	Door Rear Left // Painting	Y
131	Bumper Rear // Smart Repair Medium	Y
139	Bumper Rear / Spoiler / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
210	Door Front Right // Smart Repair Small	Y
216	Door Front Right // Polish	Y
233	Wing Front right // Painting	Y
321	Wheel Alloy Rear Left // Repair	Y

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear // Smart Repair Medium-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Rear Left // Painting-scratch



Bumper Front // Painting-scratch



Wing Front right // Painting-scratch



Door Front Right // Smart Repair Small-scratch



Door Front Right // Polish-scratch