

INSPECTION REPORT


End of contract

GENERAL INFO

File	309764
License plate	2BPL491
Vehicle identification number	SB1Z93BE10E276704
Dossier	2021 294 108
Make	Toyota Corolla TS 1.8 Hybrid D
Mileage	48012
First registration	04/02/2022
client availability date	03/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
54	Headlight / Front left / Replace	N
41	Windshield // Replace	N
42	Whiper Front // Replace	Y
72	Side View Mirror Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
222	Side View Mirror Right // Painting	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Interior Cleaning // Small-stain



Bumper Rear // Painting-scratch



Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Rear Left // Repair-scratch




Side View Mirror Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Windshield // Replace-scratch



Whiper Front // Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Headlight / Front left / Replace-cracked