

INSPECTION REPORT


End of contract

GENERAL INFO

File	307706
License plate	2BWY376
Vehicle identification number	W1K1770101N283004
Dossier	2021188069
Make	Mercedes A 180 d Bus.Sol.Aut.
Mileage	49405
First registration	25/04/2022
client availability date	13/03/2026
inspectionDate	23/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
197	Door Rear Right / Trim / Replace	N

Damage Pictures



Damage within Renta-norm-scratch



Bumper Front // Painting-scratch



Door Rear Right / Trim / Replace-cracked