

INSPECTION REPORT

End of contract

GENERAL INFO

File	314780
License plate	2BQH125
Vehicle identification number	W1N2437081J033144
Dossier	2021267042
Make	Mercedes EQA 300 Business Solu
Mileage	63442
First registration	14/02/2022
client availability date	09/06/2026
inspectionDate	15/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
136	Bumper Rear // Polish	N
153	Rear Bonnet // Painting	N
32	Front Bonnet // Painting	Y
83	Door Front Left // Painting	Y
106	Door Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
158	Rear Bonnet / 3rd Stoplight / Replace	N
184	Wing Rear Right // Repair & Painting	Y
193	Door Rear Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y

Damage Pictures




Door Front Right // Smart Repair Small-scratch



Door Rear Right // Painting-scratch





Door Rear Left // Polish-scratch



Door Front Left // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Front Bonnet // Painting-stone chipping



Rear Bonnet / 3rd Stoplight / Replace-scratch



Bumper Rear // Polish-scratch



Rear Bonnet // Painting-scratch