

INSPECTION REPORT




End of contract

GENERAL INFO

File	312619
License plate	2BGR082
Vehicle identification number	W1N2476121W163173
Dossier	2021 103 083
Make	Mercedes GLB 200d Business Sol
Mileage	200566
First registration	18/11/2021
client availability date	13/08/2026
inspectionDate	19/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
197	Door Rear Right / Trim / Replace	Y
217	Door Front Right / Trim / Replace	Y
133	Bumper Rear // Painting	N
139	Bumper Rear / Spoiler / Replace	N
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	Y
63	Wing Front Left // Painting	Y
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
107	Door Rear Left / Trim / Replace	Y
113	Wing Rear Left // Painting	Y
124	Light / Rear left / Replace	N
159	Rear Bonnet / Rear Window / Replace	Y
162	Roof // Painting	Y
169	Rear Bonnet / Spoiler / Replace & Painting	Y
194	Door Rear Right // Repair & Painting	Y
211	Door Front Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	Y
237	Wing Front right / Trim / Replace	N
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	Y
431	Seat Rear Left // Repair	Y
453	Seat Rear Right / Rear Coating / Replace	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
534	Trunk Compartment / Carpet / Replace	Y

539	Trunk Compartment / Back Coating / Replace	Y
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
554	Central Console // Replace Completely	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Interior // Repair 1-Incinerated



Interior Cleaning // Small-dirty



Dashboard / Steering Wheel / Replace-worn



Front Bonnet // Painting-stone chipping



Bumper Front / Spoiler / Replace-Chipped paint



Wheel Two Tone Rear Left // Repair-Chipped paint



Wing Front right / Trim / Replace-bad position




Bumper Front / Trim Right / Replace-scratch




Door Rear Left / Trim / Replace-scratch





Rear Bonnet / Spoiler / Replace & Painting-scratch



Roof // Painting-scratch



Light / Rear left / Replace-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch




Seat Front Left // Repair-scratch



Seat Rear Right / Rear Coating / Replace-scratch



Central Console // Replace Completely-scratch



Seat Rear Left // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch




Door Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left // Painting-scratch



Bumper Front // Repair & Painting-scratch






Wheel Two Tone Front Right // Repair-scratch



Door Rear Right // Repair & Painting-scratch + dent



Interior / Side Cover rear Seat / Replace-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Smart Repair Medium-scratch




Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Trunk Compartment / Back Coating / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Compartment / Carpet / Replace-scratch



Door Front Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Bumper Rear // Painting-scratch



Bumper Rear / Spoiler / Replace-cracked