

INSPECTION REPORT

End of contract

GENERAL INFO

File	321265
License plate	1XPX188
Vehicle identification number	YV1XZBBVFL2312446
Dossier	2019274066
Make	Volvo XC40 T5 PHEV Inscription
Mileage	141710
First registration	03/03/2020
client availability date	04/09/2026
inspectionDate	09/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	N
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
159	Rear Bonnet / Rear Window / Replace	N
180	Wing Rear Right // Smart Repair Small	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch





Rear Bonnet / Rear Window // Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch



Wing Rear Right // Smart Repair Small-dent



Seat Front Left / Bottom Coating / Replace-worn



Bumper Front / Spoiler / Replace-bad position