

INSPECTION REPORT


End of contract

GENERAL INFO

File	310507
License plate	NN4635
Vehicle identification number	W1N2539151V294562
Dossier	2020 287 011
Make	Mercedes GLC 220d 194 4M Bus S
Mileage	178378
First registration	16/04/2021
client availability date	14/04/2026
inspectionDate	17/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
16	Bumper Front // Polish	Y
41	Windshield // Replace	N
78	Side View Mirror Left / Direction Indicator / Replace	N
95	Rocker Panel Left // Polish	Y
100	Door Rear Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
168	Roof / Medium Panoramic Roof / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Interior // Repair 1-missing



Rear Bonnet // Polish-scratch



Roof / Medium Panoramic Roof / Replace-scratch




Bumper Rear // Polish-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch




Light / Rear Left On Rear Bonnet / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Front // Polish-scratch




Windshield // Replace-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Rocker Panel Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Interior / Side Cover rear Seat / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wing Rear Left // Smart Repair Small-dent



Door Rear Left // Smart Repair Small-dent



Side View Mirror Right // Painting-scratch



Side View Mirror Right / Direction Indicator / Replace-cracked