

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	310406
License plate	MA6784
Vehicle identification number	YV1UZK5V8R1867008
Dossier	2023125009
Make	Volvo XC60 B4 197MHEV Core A
Mileage	42468
First registration	07/02/2024
client availability date	13/04/2026
inspectionDate	14/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	N
104	Door Rear Left // Repair & Painting	N
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
194	Door Rear Right // Repair & Painting	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
641	Rear Right Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	Y
860	Interior Cleaning // Small	N



## Damage Pictures



Bumper Rear // Painting-scratch



Rear Bonnet // Polish-scratch




Door Front Right // Polish-scratch



Wing Front right // Polish-scratch




Side View Mirror Left // Painting-scratch




Rear Right Door Interior Coating // Repair-scratch



Rear Right Door Interior Coating // Repair-scratch



Door Front Left // Smart Repair Small-dent



Door Rear Left // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain