

INSPECTION REPORT

End of contract

GENERAL INFO

File	308707
License plate	VX6106
Vehicle identification number	VSSZZKJZNR050040
Dossier	2022189010
Make	Seat Ibiza 1.0TSi 80 Xcellence
Mileage	80301
First registration	27/07/2022
client availability date	20/03/2026
inspectionDate	23/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14 Bumper Front // Repair & Painting		N
194 Door Rear Right // Repair & Painting		Y
214 Door Front Right // Repair & Painting		N

Damage Pictures



Damage within Renta-norm-scratch



Bumper Front // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent