

INSPECTION REPORT

End of contract

GENERAL INFO

File	317435
License plate	2CBZ402
Vehicle identification number	KMHC851CGNU287846
Dossier	2021319117
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	150355
First registration	30/05/2022
client availability date	06/07/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
312	Wheel Alloy Front Left // Replace	N
314	Wheel Front Left / Wheel Cover / Replace	N
103	Door Rear Left // Painting	N
114	Wing Rear Left // Repair & Painting	N
14	Bumper Front // Repair & Painting	N
234	Wing Front right // Repair & Painting	N
31	Front Bonnet // Smart Repair Small	N
40	Windshield // Repair	Y
87	Door Front Left / Trim / Replace	N
133	Bumper Rear // Painting	N
139	Bumper Rear / Spoiler / Replace	Y
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
163	Roof // Repair & Painting	Y
165	Roof // Polish	Y
180	Wing Rear Right // Smart Repair Small	N
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	N
257	Front / Towing Cover / Replace	N
321	Wheel Alloy Rear Left // Repair	N
342	Wheel Alloy Front Right // Replace	N
453	Seat Rear Right / Rear Coating / Replace	Y
554	Central Console // Replace Completely	Y
564	Dashboard // Replace Completely	Y
624	Front Right Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Roof // Repair & Painting-scratch + dent



Rear Left Door Interior Coating // Replace Completely-scratch



Central Console // Replace Completely-scratch



Wing Rear Right // Smart Repair Small-dent



Front Bonnet // Smart Repair Small-dent



Wheel Alloy Front Right // Replace-scratch



Side View Mirror Right // Painting-scratch




Door Front Right // Smart Repair Small-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Dashboard // Replace Completely-scratch




Seat Rear Right / Rear Coating / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Roof // Polish-scratch



Front / Towing Cover / Replace-scratch



Rear Bonnet // Polish-scratch



Door Front Left / Trim / Replace-scratch



Roof // Smart Repair Medium-scratch



Wheel Alloy Rear Left // Repair-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear // Painting-bad repair



Windshield // Repair-bad repair





Interior Cleaning // Small-stain



Wheel Front Left / Wheel Cover / Replace-scratch



Wheel Alloy Front Left // Replace-scratch + dent



Door Rear Left // Painting-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-scratch + dent