

INSPECTION REPORT

End of contract


GENERAL INFO

File	318353
License plate	2BBD922
Vehicle identification number	VF3LRHNSJMS198092
Dossier	2021 110 116
Make	Peugeot 308 SW 1.2 130 Allure
Mileage	52752
First registration	16/09/2021
client availability date	16/07/2026
inspectionDate	10/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
78	Side View Mirror Left / Direction Indicator / Replace	N
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
161	Roof // Smart Repair Medium	Y
184	Wing Rear Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
264	Foglight Front Left // Replace	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
346	Tyre Front Right // Replace	N
431	Seat Rear Left // Repair	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
774	Interior / Side Cover rear Seat / Replace	Y
840	Interior Cleaning // Large	N

Damage Pictures





Bumper Rear // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch




Bumper Front // Smart Repair Medium-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Seat Rear Left // Repair-scratch



Dashboard / Steering Wheel / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch




Roof // Smart Repair Medium-dent



Wing Rear Right // Repair & Painting-scratch + dent



Foglight Front Left // Replace-cracked



Side View Mirror Left / Direction Indicator / Replace-cracked



Interior // Repair 1-missing



Interior Cleaning // Large-dirty



Tyre Front Right // Replace-tear



Wing Rear Left // Painting-Chipped paint