

INSPECTION REPORT



End of contract

GENERAL INFO

File	320003
License plate	1YVL952
Vehicle identification number	TMBJG7NX3MY085082
Dossier	2020247031
Make	Skoda Oct.Com.2.0TDI 85kW Ambi
Mileage	154566
First registration	04/01/2021
client availability date	11/08/2026
inspectionDate	18/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
156	Rear Bonnet // Polish	Y
156	Rear Bonnet // Polish	Y
14	Bumper Front // Repair & Painting	N
32	Front Bonnet // Painting	N
86	Door Front Left // Polish	N
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	Y
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	N
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
199	Door Rear Right / Window / Replace	Y
210	Door Front Right // Smart Repair Small	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
413	Seat Front Left / Rear Coating / Replace	Y
422	Seat Front Right / Bottom Coating / Replace	Y
431	Seat Rear Left // Repair	Y
533	Trunk Compartment / Side Cover Right / Replace	N
538	Trunk Compartment / Boot Cover / Replace	N
565	Dashboard / Storage Tray / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	Y
648	Rear Right Door Interior Coating / Door Handle / Replace	Y

774	Interior / Side Cover rear Seat / Replace	Y
883	Key Price Range 2 //	N

Damage Pictures



Door Rear Right // Polish-scratch



Door Rear Right / Window / Replace-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Front right // Polish-scratch



Wheel Alloy Front Left // Repair-scratch




Door Front Left // Polish-scratch





Wheel Alloy Rear Left // Repair-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Interior / Side Cover rear Seat / Replace-scratch



Rear Right Door Interior Coating / Door Handle / Replace-scratch



Dashboard / Storage Tray / Replace-scratch



Seat Rear Left // Repair-scratch




Rear Left Door Interior Coating // Repair-scratch



Door Rear Left // Smart Repair Medium-dent




Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Wing Rear Right // Polish-scratch + dent




Front Bonnet // Painting-bad repair





Bumper Front // Repair & Painting-cracked




Trunk Compartment / Boot Cover / Replace-tear



Seat Front Left / Bottom Coating / Replace-worn



Seat Front Left / Rear Coating / Replace-worn



Key Price Range 2 //-worn



Seat Front Right / Bottom Coating / Replace-worn



Rear Bonnet // Polish-scratch




Bumper Rear // Polish-scratch



Light / Rear left / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Polish-scratch