

INSPECTION REPORT

End of contract

GENERAL INFO

File	308720
License plate	2CVS224
Vehicle identification number	SB1K93BE00E353936
Dossier	2022 242 094
Make	Toyota Corolla 1.8 Hybrid Dyna
Mileage	29437
First registration	14/12/2022
client availability date	20/03/2026
inspectionDate	26/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	N
801	See External Expertise	N
14	Bumper Front // Repair & Painting	N
134	Bumper Rear // Repair & Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	Y
341	Wheel Alloy Front Right // Repair	N
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Damage within Renta-norm-dent



Bumper Rear // Repair & Painting-dent




Wheel Alloy Front Right // Repair-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch








Bumper Front // Repair & Painting-dent



Side View Mirror Left / Direction Indicator / Replace-scratch



Side View Mirror Left // Painting-scratch



See External Expertise-dent