

INSPECTION REPORT

End of contract

GENERAL INFO

File	309989
License plate	JJ8551
Vehicle identification number	W0VBE8EV1M8008912
Dossier	2020 296 016
Make	Opel Astra ST 1.5D 122 Eleganc
Mileage	123607
First registration	29/04/2021
client availability date	07/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
163	Roof // Repair & Painting	N
187	Wing Rear Right / Trim / Replace	N
11	Bumper Front // Smart Repair Medium	N
41	Windshield // Replace	Y
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	N
163	Roof // Repair & Painting	N
184	Wing Rear Right // Repair & Painting	N
210	Door Front Right // Smart Repair Small	Y
234	Wing Front right // Repair & Painting	N
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Windshield // Replace-glass damage



Interior Cleaning // Small-stain



Rear Bonnet // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Front Right // Repair-scratch




Door Front Right // Smart Repair Small-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch




Wheel Alloy Front Left // Repair-scratch




Bumper Front // Smart Repair Medium-scratch



Bumper Rear // Painting-scratch






Roof // Repair & Painting-dent



Wing Front right // Repair & Painting-dent



Wing Rear Right // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-scratch + dent



Roof // Repair & Painting-scratch + dent