

INSPECTION REPORT


End of contract

GENERAL INFO

File	319555
License plate	2ARF679
Vehicle identification number	TMBJF7NU2M5044002
Dossier	2021 028 197
Make	Skoda Karoq 2.0TDi 85kW Clever
Mileage	99242
First registration	21/06/2021
client availability date	21/08/2026
inspectionDate	27/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
193	Door Rear Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y
236	Wing Front right // Polish	Y
413	Seat Front Left / Rear Coating / Replace	Y
423	Seat Front Right / Rear Coating / Replace	Y

Damage Pictures




Bumper Rear / Lower Cover Not Painted / Replace-scratch




Wing Front right // Polish-scratch



Door Front Left // Smart Repair Small-scratch




Door Rear Left // Polish-scratch



Door Rear Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Door Front Right // Smart Repair Small-dent



Seat Front Right / Rear Coating / Replace-worn



Seat Front Left / Rear Coating / Replace-worn