



ARVAL
BNP PARIBAS GROUP

LA7431

INSPECTION REPORT

End of contract

GENERAL INFO

File	319681
License plate	LA7431
Vehicle identification number	W1NKM0FB6RF128283
Dossier	2023041019
Make	Mercedes GLC 220d 197 Busin.Li
Mileage	23112
First registration	04/01/2024
client availability date	06/08/2026
inspectionDate	11/08/2026



CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	



DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
133	Bumper Rear // Painting	Y
150	Rear Bonnet // Smart Repair Small	N
201	Rocker Panel Right // Smart Repair Medium	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wheel Two Tone Rear Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Rear Bonnet // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent