

INSPECTION REPORT


End of contract


GENERAL INFO

File	315702
License plate	GV7829
Vehicle identification number	VR3UHZKXZNT105624
Dossier	2022313004
Make	Peugeot E-208 136 GT Pack 5d
Mileage	88202
First registration	17/11/2022
client availability date	18/06/2026
inspectionDate	24/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
132	Bumper Rear // Smart Repair Large	N
139	Bumper Rear / Spoiler / Replace	N
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch



Wing Front right // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear // Smart Repair Large-scratch