

INSPECTION REPORT

End of contract

GENERAL INFO

File	316231
License plate	TB6180
Vehicle identification number	ZARNASAA4N3057464
Dossier	2023118018
Make	Alfa Romeo Tonale 1.5 MHEV 130
Mileage	89406
First registration	08/12/2023
client availability date	25/06/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
134	Bumper Rear // Repair & Painting	N
184	Wing Rear Right // Repair & Painting	N
187	Wing Rear Right / Trim / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
258	Towing Cover Rear // Replace	N
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
150	Rear Bonnet // Smart Repair Small	N
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
194	Door Rear Right // Repair & Painting	Y
213	Door Front Right // Painting	N
233	Wing Front right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
431	Seat Rear Left // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
644	Rear Right Door Interior Coating // Replace Completely	N
881	Key Price Range 1 //	N

Damage Pictures



See External Expertise-



Light / Rear Right / Replace-scratch



Light / Rear left / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Door Front Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Front Left // Repair-scratch





Wheel Two Tone Rear Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Seat Rear Left // Repair-scratch



Wing Rear Left // Smart Repair Small-dent



Rear Bonnet // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent





Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Repair & Painting-scratch + dent



Door Rear Left // Painting-bad repair



Door Front Left // Painting-bad repair




Wing Front right // Painting-bad repair



Wing Rear Right / Trim / Replace-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch



Towing Cover Rear // Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch