

INSPECTION REPORT

End of contract

GENERAL INFO

File	319323
License plate	2BVD852
Vehicle identification number	VR3FPHNSLMY533123
Dossier	2022080153
Make	Peugeot 308 1.2 130 Allure Pac
Mileage	37999
First registration	04/04/2022
client availability date	15/07/2026
inspectionDate	19/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
104	Door Rear Left // Repair & Painting	N
184	Wing Rear Right // Repair & Painting	N
222	Side View Mirror Right // Painting	Y
223	Side View Mirror Right // Replace Not Painted	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures




Wheel Two Tone Rear Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch




Side View Mirror Right // Painting-scratch




Side View Mirror Right // Replace Not Painted-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Rear Left // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent