

INSPECTION REPORT



End of contract

GENERAL INFO

File	314658
License plate	2ALE754
Vehicle identification number	VR3ECYHZ2MJ660594
Dossier	2021033136
Make	Peugeot Rifter 1.5BHDi 130 All
Mileage	199582
First registration	30/04/2021
client availability date	05/06/2026
inspectionDate	17/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
137	Bumper Rear // Replace without painting	N
174	Light / Rear Right / Replace	N
184	Wing Rear Right // Repair & Painting	N
187	Wing Rear Right / Trim / Replace	N
73	Side View Mirror Left // Replace Not Painted	N
75	Side View Mirror Left // Polish	N
107	Door Rear Left / Trim / Replace	N
117	Wing Rear Left / Trim / Replace	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
145	Back Side / Logo / Replace	N
154	Rear Bonnet // Repair & Painting	N
317	Spare Wheel // Replace	Y
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
418	Seat Front Left / Armrest / Replace	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
568	Dashboard / Ventilation Outlet / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
840	Interior Cleaning // Large	N

Damage Pictures



Bumper Front / Lower Cover Not Painted / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch




Back Side / Logo / Replace-missing



Interior Cleaning // Large-stain



Seat Front Left / Armrest / Replace-worn




Dashboard / Steering Wheel / Replace-worn



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Dashboard / Ventilation Outlet / Replace-scratch



Rear Bonnet // Repair & Painting-dent



Wing Rear Right / Trim / Replace-scratch



Light / Rear Right / Replace-scratch



Bumper Rear // Replace without painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Side View Mirror Left // Replace Not Painted-scratch



Side View Mirror Left // Polish-scratch



Wing Rear Left / Trim / Replace-scratch



Door Rear Left / Trim / Replace-scratch