

INSPECTION REPORT


End of contract

GENERAL INFO

File	322004
License plate	2BWF280
Vehicle identification number	TMBJJ7NS7N8032019
Dossier	2021 180 114
Make	Skoda Kod.2.0CRTDI 110kW Cleve
Mileage	161448
First registration	14/04/2022
client availability date	10/09/2026
inspectionDate	22/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
237	Wing Front right / Trim / Replace	N
271	Bumper Front / Trim Left / Replace	N
32	Front Bonnet // Painting	N
72	Side View Mirror Left // Painting	N
81	Door Front Left // Smart Repair Medium	Y
82	Door Front Left // Smart Repair Large	N
104	Door Rear Left // Repair & Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
154	Rear Bonnet // Repair & Painting	N
162	Roof // Painting	N
169	Rear Bonnet / Spoiler / Replace & Painting	N
196	Door Rear Right // Polish	Y
210	Door Front Right // Smart Repair Small	Y
331	Wheel Alloy Rear Right // Repair	Y
431	Seat Rear Left // Repair	N


Damage Pictures




Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Door Front Left // Smart Repair Large-scratch



Seat Rear Left // Repair-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch




Wheel Alloy Rear Right // Repair-scratch



Door Rear Right // Polish-scratch




Door Front Right // Smart Repair Small-scratch



Door Rear Left // Repair & Painting-scratch + dent



Rear Bonnet // Repair & Painting-Chemical reaction



Roof // Painting-Chemical reaction



Rear Bonnet / Spoiler / Replace & Painting-Chemical reaction



Front Bonnet // Painting-Chemical reaction



Bumper Front / Spoiler / Replace-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front // Painting-scratch



Bumper Front / Trim Left / Replace-scratch