

INSPECTION REPORT


End of contract

GENERAL INFO

File	321489
License plate	EU9740
Vehicle identification number	NLHBN51GANZ189404
Dossier	2021329020
Make	Hyundai i20 1.0i 100 Twist
Mileage	174994
First registration	22/08/2022
client availability date	03/09/2026
inspectionDate	07/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
161	Roof // Smart Repair Medium	N
163	Roof // Repair & Painting	N
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	N
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	N
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
158	Rear Bonnet / 3rd Stoplight / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	N
314	Wheel Front Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
346	Tyre Front Right // Replace	N
533	Trunk Compartment / Side Cover Right / Replace	Y
561	Dashboard // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Interior Cleaning // Small-dirty



Tyre Front Right // Replace-tear



Door Front Left / Trim / Replace-Chipped paint



Bumper Front / Spoiler / Replace-bad position



Dashboard // Repair-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Light / Rear Right / Replace-scratch



Rear Bonnet / 3rd Stoplight / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Bumper Front // Painting-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch




Trunk Compartment / Side Cover Right / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Dashboard / Steering Wheel / Replace-scratch



Door Front Left // Smart Repair Small-dent



Roof // Smart Repair Medium-scratch



Roof // Repair & Painting-dent