

INSPECTION REPORT



End of contract


GENERAL INFO

File	309876
License plate	LA7573
Vehicle identification number	W1NGM2BB7PA031336
Dossier	2023213003
Make	Mercedes EQE SUV 350+ Business
Mileage	51107
First registration	31/01/2024
client availability date	01/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
124	Light / Rear left / Replace	Y
136	Bumper Rear // Polish	Y
158	Rear Bonnet / 3rd Stoplight / Replace	Y
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	Y
211	Door Front Right // Smart Repair Medium	Y
341	Wheel Alloy Front Right // Repair	Y
344	Wheel Front Right / Wheel Cover / Replace	N
421	Seat Front Right // Repair	N
543	Interior // Ionization Odor	N
614	Front Left Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures




Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Alloy Front Right // Repair-scratch




Front Left Door Interior Coating // Replace Completely-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Seat Front Right // Repair-scratch



Door Front Right // Smart Repair Medium-scratch



Rear Right Door Interior Coating // Replace Completely-scratch




Roof // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Light / Rear Right / Replace-scratch



Rear Bonnet / 3rd Stoplight / Replace-scratch



Bumper Rear // Polish-scratch



Light / Rear left / Replace-scratch



Wing Rear Left // Polish-scratch



Door Rear Left // Polish-scratch