

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	306827
License plate	2AWX742
Vehicle identification number	KMHC851CGMU247102
Dossier	2021161075
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	127644
First registration	23/08/2021
client availability date	04/03/2026
inspectionDate	11/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
184	Wing Rear Right // Repair & Painting	N
193	Door Rear Right // Painting	N
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	N
12	Bumper Front // Smart Repair Large	N
18	Bumper Front / Spoiler / Replace	N
28	Front / Calendar / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
113	Wing Rear Left // Painting	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
203	Rocker Panel Right // Repair & Painting	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
421	Seat Front Right // Repair	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	N
538	Trunk Compartment / Boot Cover / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N
637	Rear Left Door Interior Coating / Grid Loudspeaker / Replace	N
641	Rear Right Door Interior Coating // Repair	N
647	Rear Right Door Interior Coating / Grid Loudspeaker / Replace	N
860	Interior Cleaning // Small	N

## Damage Pictures



Damage within Renta-norm-scratch



Interior Cleaning // Small-stain




Front / Calendar / Replace-Chipped paint



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent



Wheel Alloy Front Left // Repair-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Seat Front Right // Repair-scratch



Rear Right Door Interior Coating // Repair-scratch




Rear Right Door Interior Coating / Grid Loudspeaker / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch




Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Boot Cover / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Bonnet // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch




Wheel Alloy Rear Left // Repair-scratch




Rear Left Door Interior Coating // Repair-scratch




Rear Left Door Interior Coating / Grid Loudspeaker / Replace-scratch





Wing Rear Left // Painting-scratch




Door Rear Left // Smart Repair Medium-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Door Front Right / Trim / Replace-scratch



Door Front Right // Repair & Painting-Incinerated