

INSPECTION REPORT



End Of Contract

GENERAL INFO

File	284570
License plate	QM9984
Vehicle identification number	WAUZZZF45KA083897
Dossier	2019039022
Make	Audi A4 Av 40TDi 190 Sport Qua
Mileage	195422.00
First registration	28/06/2019
	06/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
148	Back Side / Reflector R / Replace	N
801	See External Expertise	N
11	Bumper Front // Smart Repair Medium	N
33	Front Bonnet // Repair & Painting	Y
54	Headlight / Front left / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
194	Door Rear Right // Repair & Painting	Y
321	Wheel Alloy Rear Left // Repair	Y
631	Rear Left Door Interior Coating // Repair	Y
883	Key Price Range 2 //	N


Damage Pictures



Rear Left Door Interior Coating // Repair-scratch




Light / Rear Right / Replace-scratch




Light / Rear Right On Rear Bonnet / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Front Bonnet // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Wheel Alloy Rear Left // Repair-bad repair



Key Price Range 2 //-missing



Headlight / Front left / Replace-scratch



Bumper Front // Smart Repair Medium-scratch



Bumper Rear // Repair & Painting-scratch + dent



Back Side / Reflector R / Replace-scratch



See External Expertise-