

INSPECTION REPORT

End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 306742 |
| License plate | 2CPY111 |
| Vehicle identification number | VR3USHNSSNJ662384 |
| Dossier | 2022256098 |
| Make | Peugeot 2008 1.2 96kW Allure E |
| Mileage | 131517 |
| First registration | 12/10/2022 |
| client availability date | 02/03/2026 |
| inspectionDate | 11/03/2026 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | Y | |
| Registration Part 2 | | N | |
| Keys | 1 | Y | |
| Spare wheel | | N | |
| Towbar (+keys) | | N | |
| Certificate of conformity | | Y | |
| Registration certificate | | Y | |
| Repair kit | | Y | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | N | |





DAMAGES

| Damages | Type | Acceptable |
|---------|---|------------|
| 13 | Bumper Front // Painting | N |
| 272 | Bumper Front / Trim Right / Replace | N |
| 631 | Rear Left Door Interior Coating // Repair | Y |
| 634 | Rear Left Door Interior Coating // Replace Completely | Y |
| 213 | Door Front Right // Painting | Y |
| 231 | Wing Front right // Smart Repair Medium | Y |
| 18 | Bumper Front / Spoiler / Replace | N |
| 38 | Front Bonnet / Insulation / Replace | Y |
| 67 | Wing Front Left / Trim / Replace | Y |
| 84 | Door Front Left // Repair & Painting | N |
| 87 | Door Front Left / Trim / Replace | N |
| 91 | Rocker Panel Left // Smart Repair Medium | N |
| 104 | Door Rear Left // Repair & Painting | N |
| 117 | Wing Rear Left / Trim / Replace | Y |
| 159 | Rear Bonnet / Rear Window / Replace | Y |
| 187 | Wing Rear Right / Trim / Replace | N |
| 194 | Door Rear Right // Repair & Painting | Y |
| 282 | Bumper Rear / Trim Center / Replace | Y |
| 340 | Wheel Two Tone Front Right // Repair | N |
| 594 | Trunk Lid Interior Coating / Complete Panel / Replace | Y |
| 774 | Interior / Side Cover rear Seat / Replace | Y |
| 860 | Interior Cleaning // Small | N |
| 883 | Key Price Range 2 // | N |

Damage Pictures





Damage within Renta-norm-



Bumper Front / Spoiler / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch




Wing Rear Right / Trim / Replace-scratch





Door Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Door Front Left / Trim / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Wing Front Left / Trim / Replace-scratch




Bumper Front // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wing Front right // Smart Repair Medium-scratch



Door Front Right // Painting-scratch