

INSPECTION REPORT


End of contract

GENERAL INFO

File	313813
License plate	NH8305
Vehicle identification number	W1K2054141G112456
Dossier	2021344001
Make	Mercedes C Cabrio 220d 194 AMG
Mileage	149558
First registration	13/05/2022
client availability date	27/05/2026
inspectionDate	29/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
80	Door Front Left // Smart Repair Small	Y
98	Rocker Panel Left / Cover Not Painted / Replace	Y
110	Wing Rear Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	N
184	Wing Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	Y
236	Wing Front right // Polish	Y
272	Bumper Front / Trim Right / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
421	Seat Front Right // Repair	N
614	Front Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Rear // Painting-scratch



Light / Rear Right / Replace-scratch



Rear Bonnet // Polish-scratch



Wing Front right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front / Trim Right / Replace-scratch



Front Bonnet // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Seat Front Right // Repair-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Rocker Panel Left / Cover Not Painted / Replace-dent



Door Front Right // Smart Repair Small-dent



Wing Rear Left // Smart Repair Small-dent



Wing Rear Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Interior Cleaning // Small-stain