

INSPECTION REPORT

End of contract

GENERAL INFO

File	321102
License plate	1YVK432
Vehicle identification number	VR3EFYHWCLN542648
Dossier	2020195019
Make	Peugeot Part.1.5BHDi 75 L1 L P
Mileage	176419
First registration	04/01/2021
client availability date	02/09/2026
inspectionDate	10/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
28	Front / Calendar / Replace	N
244	Light / Front Right / Replace	N
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	N
124	Light / Rear left / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
303	Rear Loading Door Right // Painting	N
66	Wing Front Left // Polish	Y
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
114	Wing Rear Left // Repair & Painting	Y
163	Roof // Repair & Painting	N
174	Light / Rear Right / Replace	N
186	Wing Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
293	Rear Loading Door Left // Painting	N
540	Interior // Repair 1	Y
619	Front Left Door Interior Coating / Control Module / Replace	N
860	Interior Cleaning // Small	N


Damage Pictures



Light / Rear Right / Replace-cracked



Interior Cleaning // Small-stain



Front Left Door Interior Coating / Control Module / Replace-bad position



Rear Loading Door Left // Painting-bad repair



Wing Rear Left // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-dent



Interior // Repair 1-scratch




Wing Rear Right // Polish-scratch






Wing Front Left // Polish-scratch




Door Front Left / Trim / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Roof // Repair & Painting-dent



Bumper Front // Repair & Painting-scratch + dent




Front / Calendar / Replace-bad repair



Light / Front Right / Replace-bad repair



Bumper Front / Lower Cover Not Painted / Replace-Splashes



Door Front Right / Trim / Replace-bad repair




Door Rear Right // Repair & Painting-dent



Door Front Right // Repair & Painting-dent



Bumper Rear / Lower Cover Not Painted / Replace-bad repair



Rear Loading Door Right // Painting-bad repair



Light / Rear left / Replace-bad repair