

INSPECTION REPORT



End Of Contract

GENERAL INFO

File	277641
License plate	1WAZ452
Vehicle identification number	WAUZZZ8V3KA080342
Dossier	2019 044 074
Make	Audi A3SB 30 TDi 85kW Bus.Ed.S
Mileage	169533.00
First registration	10/04/2019
	12/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
103	Door Rear Left // Painting	N
114	Wing Rear Left // Repair & Painting	N
136	Bumper Rear // Polish	Y
203	Rocker Panel Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures




Bumper Rear // Polish-scratch





Wheel Alloy Rear Right // Repair-scratch




Wheel Alloy Front Left // Repair-scratch





Door Rear Left // Painting-scratch





Wheel Alloy Front Right // Repair-scratch



Rocker Panel Right // Repair & Painting-dent



Door Front Right // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Bumper Front // Replace & Painting-cracked



Interior Cleaning // Small-dirty