

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	296707
License plate	2AGK014
Vehicle identification number	VR3USHNSSMJ627742
Dossier	1000 191 696
Make	Peugeot 2008 1.2 96kW Active P
Mileage	41739
First registration	25/03/2021
client availability date	17/10/2025
inspectionDate	11/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
103	Door Rear Left // Painting	N
196	Door Rear Right // Polish	Y
457	Seat Rear Right / Headrest / Replace	N
535	Trunk Compartment / Window Shelf / Replace	N
631	Rear Left Door Interior Coating // Repair	N
883	Key Price Range 2 //	N

## Damage Pictures



Damage within Renta-norm-scratch



Rear Left Door Interior Coating // Repair-scratch



Trunk Compartment / Window Shelf / Replace-missing



Seat Rear Right / Headrest / Replace-missing



Door Rear Left // Painting-scratch



Door Rear Right // Polish-scratch