

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	309706
License plate	TT1115
Vehicle identification number	W1N2539131G001910
Dossier	2021076026
Make	Mercedes GLC 200d 163 Aut
Mileage	109433
First registration	20/01/2022
client availability date	01/04/2026
inspectionDate	08/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
139	Bumper Rear / Spoiler / Replace	Y
282	Bumper Rear / Trim Center / Replace	Y
111	Wing Rear Left // Smart Repair Medium	N
124	Light / Rear left / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
551	Central Console // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

## Damage Pictures



Wing Rear Left // Smart Repair Medium-scratch + dent



Central Console // Repair-scratch



Light / Rear left / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch + dent