

INSPECTION REPORT

End of contract


GENERAL INFO

File	321767
License plate	AS1664
Vehicle identification number	W1KEG2FB5PF020327
Dossier	2022249019
Make	Mercedes EQE 350 292 Luxury Li
Mileage	90735
First registration	14/03/2023
client availability date	08/09/2026
inspectionDate	10/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
29	Front / Park Assist Sensor / Replace	N
271	Bumper Front / Trim Left / Replace	N
273	Bumper Front / Grid Left / Replace	N
133	Bumper Rear // Painting	N
174	Light / Rear Right / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Light / Rear Right / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Front / Park Assist Sensor / Replace-scratch




Bumper Front / Lower Cover Not Painted / Replace-scratch + dent



Bumper Front / Grid Left / Replace-cracked



Bumper Front / Trim Left / Replace-cracked



Bumper Front // Replace & Painting-cracked