

INSPECTION REPORT


End of contract


GENERAL INFO

File	318577
License plate	2CGH370
Vehicle identification number	VF3YCCPFC12V39255
Dossier	2022132119
Make	Peugeot Box.HDI 335 L3H2 165 P
Mileage	84509
First registration	14/07/2022
client availability date	22/07/2026
inspectionDate	26/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
114	Wing Rear Left // Repair & Painting	N
137	Bumper Rear // Replace without painting	N
891	Lettering Removal 15min	N
17	Bumper Front // Replace without painting	Y
41	Windshield // Replace	N
93	Rocker Panel Left // Repair & Painting	N
257	Front / Towing Cover / Replace	N
314	Wheel Front Left / Wheel Cover / Replace	Y
324	Wheel Rear Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
422	Seat Front Right / Bottom Coating / Replace	N
564	Dashboard // Replace Completely	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	Y

Damage Pictures



Wheel Rear Left / Wheel Cover / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Bumper Front // Replace without painting-scratch



Rocker Panel Left // Repair & Painting-scratch + dent



Seat Front Right / Bottom Coating / Replace-Incinerated



Windshield // Replace-glass damage



Front / Towing Cover / Replace-missing



Wheel Front Right / Wheel Cover / Replace-missing



Wheel Rear Right / Wheel Cover / Replace-missing



Interior Cleaning // Small-stain



Dashboard // Replace Completely-hole



Bumper Rear // Replace without painting-cracked



Wing Rear Left // Repair & Painting-scratch + dent



Lettering Removal 15min-