

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	308062
License plate	MA6703
Vehicle identification number	YV1UZK5V8R1856106
Dossier	2023208014
Make	Volvo XC60 B4 197MHEV Core A
Mileage	66299
First registration	19/01/2024
client availability date	16/03/2026
inspectionDate	17/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
40	Windshield // Repair	Y
133	Bumper Rear // Painting	N

## Damage Pictures



Damage within Renta-norm-scratch



Bumper Rear // Painting-scratch



Windshield // Repair-glass damage