

INSPECTION REPORT



End of contract


GENERAL INFO

File	321810
License plate	2CKP469
Vehicle identification number	VSSZZZKLZNR068074
Dossier	2022235149
Make	Seat Leon 1.0eTSI 110 Move! DS
Mileage	96059
First registration	25/08/2022
client availability date	08/09/2026
inspectionDate	18/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
40	Windshield // Repair	Y
54	Headlight / Front left / Replace	Y
72	Side View Mirror Left // Painting	Y
133	Bumper Rear // Painting	N
184	Wing Rear Right // Repair & Painting	N
190	Door Rear Right // Smart Repair Small	Y
230	Wing Front right // Smart Repair Small	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
531	Trunk Compartment // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	N
540	Interior // Repair 1	N
565	Dashboard / Storage Tray / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
883	Key Price Range 2 //	N

Damage Pictures



Headlight / Front left / Replace-scratch



Dashboard / Storage Tray / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Interior // Repair 1-scratch



Side View Mirror Left // Painting-scratch



Bumper Front // Painting-scratch



Wheel Alloy Front Right // Repair-scratch




Door Rear Right // Smart Repair Small-dent



Wing Front right // Smart Repair Small-dent



Wing Rear Right // Repair & Painting-scratch + dent



Key Price Range 2 //-bad repair



Windshield // Repair-cracked



Trunk Compartment // Repair-cracked