

# INSPECTION REPORT

End of contract


## GENERAL INFO

File	310663
License plate	FU9884
Vehicle identification number	VF3MCYHZUMS206487
Dossier	2021 055 035
Make	Peugeot 5008 1.5HDi 130 Roadtr
Mileage	177528
First registration	07/10/2021
client availability date	15/04/2026
inspectionDate	17/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	N
84	Door Front Left // Repair & Painting	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
110	Wing Rear Left // Smart Repair Small	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	N
194	Door Rear Right // Repair & Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	N
421	Seat Front Right // Repair	Y
556	Central Console / Cover Armrest / Replace Cover Armrest	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	Y

## Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch




Light / Rear Left On Rear Bonnet / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch




Door Front Left / Trim / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch




Rear Left Door Interior Coating // Replace Completely-scratch



Seat Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Door Rear Right // Repair & Painting-dent



Roof // Smart Repair Medium-dent



Wing Rear Left // Smart Repair Small-dent



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Windshield // Replace-cracked



Wheel Two Tone Rear Right // Repair-Chemical reaction



Central Console / Cover Armrest / Replace Cover Armrest-tear



Seat Front Left / Bottom Coating / Replace-tear

