

INSPECTION REPORT



End Of Contract

GENERAL INFO

File	281360
License plate	2CKG252
Vehicle identification number	WAUZZZF3XP1018462
Dossier	2022171085
Make	Audi Q3 45 TFSie PHEV 180kW St
Mileage	30068.00
First registration	23/08/2022
	30/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
213	Door Front Right // Painting	N

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Front Right // Painting-scratch + dent



Bumper Rear // Painting-scratch + dent